GM CUSTOMER CARE AND AFTERSALES DCS3212 URGENT - DISTRIBUTE IMMEDIATELY

Date: July 8, 2014

Subject: Stop Delivery Order Revised

Upcoming Safety Recall 14172

Additional Information

Models: 2003-2014 Cadillac CTS

2004-2006 Cadillac SRX Equipped with Key Ignition

To: All Cadillac Dealers

Attention: Dealer, Dealer Principal, General Manager, General Sales

Manager, New Vehicle Sales Manager, Parts and Service Director,

Used Vehicle Sales Manager, and Service Manager

STOP DELIVERY ORDER

Note that only Cadillac CTS vehicles equipped with a key ignition are involved in this stop delivery. These vehicles can be identified by a "D" in the fourth position of the Vehicle Identification Number (VIN). The next generation Cadillac CTS is not involved in this stop delivery. These vehicles are equipped with a push start button and can be identified by an "A" in the fourth position of the VIN.

Effective immediately, stop the delivery of certain 2003-2014 Cadillac CTS and 2004-2006 Cadillac SRX vehicles in new or used vehicle inventory if equipped with a key ignition. Vehicles equipped with the push start button are not involved in this stop delivery.

If the key ring is carrying added weight and the vehicle goes off road or experiences some other jarring event, or if the driver unintentionally bumps the key ring or items attached to the key ring with their knee, the key may unintentionally move away from the "run" position. If this occurs, engine power, power steering and power braking may be affected, increasing the risk of a crash. The timing of the key movement out of the "run" position, relative to the activation of the sensing algorithm of the crash event, may result in the airbags not deploying, increasing the potential for occupant injury in certain kinds of crashes.

Customers should remove all items from their key rings, including the key fob, leaving only the ignition key. In addition it is very important that drivers adjust their seat and steering column to allow clearance between their knee and the ignition key.

Dealers are to provide two replacement key rings. Vehicles with slotted keys will also receive key inserts.

If any of these vehicles are in dealer inventory (new or used), they must be held and not delivered to customers, dealer traded, released to auction, or used for demonstration purposes until further instructions are received.

The attached list provides the VIN of identified vehicles in dealer new inventory. It is sorted by dealer Business Associate Code (BAC) for easy reference. If your dealership's BAC is not listed, then none of the involved vehicles are currently assigned to you.

Instructions for releasing the involved vehicles from this stop delivery will be provided in the near future.

END OF MESSAGE
GM CUSTOMER CARE AND AFTERSALES